



**KIM MOLTZER**

VITRINE

FRANCE, c. 1970 | CHROME-PLATED STEEL, BRASS, GLASS, LAMINATE OVER WOOD | 81 W × 20 D × 95 H IN

CONDITION

Area of loss to laminate on base at edge, and is lifting in several areas. Metal components displaying patina. Vitrine is difficult to assemble, and is wobbly. Several connections are stripped. Several scallop flakes to glass. Wear throughout entire unit. Vintage condition.